# Quick Start Guide

## 1. USB Instrument Cable Connection



**Connect USB Cable**

*Connect to Computer*

## 2. Power Cord Connection



**Connect Power Cord**

*Connect to Outlet*

## 3. Power instrument. Locate black trap, white tile and green tile in accessories drawer. Launch a Datacolor program, and calibrate* the instrument.



**Power Switch**

**Calibration Accessories**

**Part No. 019-400020, Rev B**

**\*** See User's Guide on USB Memory Stick for detailed instructions.